

OUT 61946

P 102321Z MAY 67  
 FM NPIC WASHDC  
 TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB  
 RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
 RUCVAAA/2D RTS BARKSDALE AFB LA  
 RUEPJS/DIA WASHDC  
 RUCIJRA/NAVRECONTECHSUPPCEN SUITLAND MD  
 RUEPIA/CIA WASHDC  
 RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF  
 RUCVAAA/2 AF BARKSDALE AFB LA  
 BT

SECRET CITE NPIC 0611.

15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOCR, DM 4)

2D AF (FOR DI).

1. CAMERA B 7 WAS USED ON MISSION G-959 FLOWN ON 9 MAY 1967. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. RESOLUTION AND DENSITY ARE GOOD.

B. 9R SIDE: FRAMES 894, 895 AND 896 CONTAIN MINOR DEGRADATIONS INDUCED DURING PROCESSING; WATER OR CHEMICALS WERE SPLASHED ON PORTIONS OF THESE THREE FRAMES. THERE ARE MANUFACTURING SPLICES IN FRAMES 1003 AND 1293, A HEAT SPLICE IN FRAME 857 AND BETWEEN FRAMES 601/602, AND 1670/1671.

C. 9L SIDE: THERE ARE TWO PLUS DENSITY LINES, 1.7 AND 4.5 INCHES FROM AND PARALLEL TO THE INBOARD EDGE THROUGHOUT THE MISSION. EDGE CRIMPING IS NOTED ALONG THE OUTBOARD EDGE FROM FRAME 879 TO 900. THERE IS A HEAT SPLICE IN FRAME 878.

D. BOTH SIDES: THE EVENTS COUNTER BECAME ERRATIC AFTER FRAME 358 AND EVENTUALLY STUCK AT NUMBER 408 WHERE

1967 MAY 10 23 40Z

11 MAY 1967

DISTRIBUTION		
Cy No.	Office	Action
2	File	
	OS	
	SEC BR	
	TDS	
	CSD	
	IFD	
	FO	
	RSD	
	PRIM/DB	
	TIO	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy  
Sentinel

SECRET

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

IT REMAINED FOR THE BALANCE OF THE MISSION. FRAME 704,  
708 AND 712 CONTAIN A CHANGE IN DENSITY WHICH HAS BEEN  
ATTRIBUTED TO WINDOW REFLECTIONS IN PREVIOUS EVALUATIONS.  
THE CYCLE RATE IS 4.5 SECONDS WITH APPROXIMATELY 60 PERCENT  
OVERLAP IN THE VERTICAL FRAMES. THE LAST TITLED FRAME IS  
1787.

3. POSITIVE:

- A. THE RESOLUTION AND DENSITY ARE GOOD.
- B. THE PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE APPROXIMATELY 25 PERCENT OF THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE-